



Applicant : Beijing Embfan Tech. Limited
Room 609, Unit 2, Building 5, Zhujiang Moore International
Building, No.1 Beiqing Road, Changping District, Beijing PRC.
Attn : Qin Ling

Date : Aug 18, 2023

Sample Description As Declared :

No. Of Sample : One (1)
Fibre Content : 100% Cotton
Material : Woven Fabric, Cotton Drill 32x32 With Pigment Dying
Finishing : -
End Uses : Adult's Garment
Colour : Navy
Style No. : -
Order No./PO No. : -
Buyer's Name : -
Agent's Name : -
Manufacturer's Name : -

Applicant's Provided Care Instruction/Label :-

Date Received/Date Test Started : Aug 15, 2023

Tests Conducted:


As Requested By The Applicant, For Details Refer To Attached Page(S)

Conclusion:

Colour Fastness To Washing	M
Colour Fastness To Rubbing	F
Colour Fastness To Light	#
Colour Fastness To Perspiration	M

Remark : M = Commercially Acceptable; F = Fail
= No Comment

Authorized By :
For Intertek Testing Services
(Tianjin) Ltd.



Patrick Gong
General Manager

Tests Conducted:

- 1 Colour Fastness To Washing (AS 2001.4.15-2006, Test L2, 30 Minutes Mechanical Wash At 60°C In 0.4% ECE Reference Detergent And 0.1% Sodium Perborate Test Solution With 25 Steel Balls) :

Colour Change	4
Colour Staining	
- Cotton	4-5
- Nylon	4-5

- 2 Colour Fastness To Rubbing (AS 2001.4.3-1995) :

Dry	4-5
-----	-----

- 3 Colour Fastness To Light (AS 2001.4.B02-2001, Xenon-Arc Lamp) :

After 60 Hours	
Grade	Navy 6 Blue 6 Aqua 6 Rose 6 Orange 6 Dk.Orange 6

- 4 Colour Fastness To Perspiration (AS 2001.4.E04-2005) :

	<u>Acid</u>			<u>Alkaline</u>		
	Navy	Orange	Others	Navy	Orange	Others
Colour Change	4-5	4-5	4-5	4-5	4-5	4-5
Colour Staining						
- Cotton	4-5	4-5	4-5	4-5	4-5	4-5
- Nylon	4-5	4-5	4-5	4-5	4-5	4-5

This report is made solely on the basis of your instructions and/or information and materials supplied by you. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or wilful misconduct.